

General Environmental Incident Summary

Incident: 3430 **Date/Time Notice:** 8/20/2014 **DEM Incident No:**

Responsible Party: Unknown

Date Incident: 8/8/2014 **Time Incident:** **Duration:**

County: Burleigh **Twp:** 138 **Rng:** 80 **Sec:** 7 **Qtr:**

Lat: 46.78734 **Long:** -100.81630 **Method:** Interpolation from map

Location Description: Dock slip outside of the Pier in Bismarck, ND

Submitted By: Scott Stockdill

Affiliation:

Address: 918 East Divide Ave.

City: Bismarck

State: ND

Zip:

Received By:

Contact Person:

Unknown

Unknown, ND

Distance Nearest Occupied Building:

Release Contained: No

Type of Incident: Vehicle Accident

Description of Released Contaminant: Gasoline

Volume Spilled: 15.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Boat sank in the front of the Pier Bar

Risk Evaluation:

Sunken boat is a boating hazard, however the boat was removed via crane.

of Fatalities: 0

of Injuries: 0

Affected Medium: 02 - water

Potential Environmental Impacts:

Minimal environmental impacts at location.

Action Taken or Planned:

Boat was removed with a crane and sorbent booms were put in place to contain the spill.

Wastes Disposal Location: Sorbent Booms and pads were deployed to contain and collect any product.

Agencies Involved: Local Fire Department, Local Law Enforcement

Updates

Date: 8/20/2014 ***Status:*** Reviewed - Assigned to NDDoH Division

Author: Roberts, Kris

Updated Volume:

Notes:

Incident followup was assigned to Water Quality Division. Consultant was mobilized to perform restoration.